

General Information

Date & Time: 25, Feb, 2025 09:58

Make	Toyota	Model	Vios
YOM	2024	Mileage	25,812
Registration No.	NEY3197	Chassis No.	PA1B18F36R4254781
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.6	110	105	105
2	Boot Lid	102.5	96	102	110
3	Roof	97.6	104	96	92/98
4	Left Front Fender	90.5	96	85	91
5	Left Front Door	90.2	91	85	95
6	Center Panel Left				
7	Left Rear Door	92.5	102	90	86
8	Left Back Panel	101.3	105	100	99
9	Right Front Fender	95.8	90	100	98
10	Right Front Door	87.5	86	86	91
11	Center Panel Right				
12	Right Rear Door	97.5	91	95	106
13	Right Back Panel	95.5	89	95	102

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Grime - Medium / (L) Front Seat - Grime - Minimal / Ceiling - Grime - Minimal	Remarks (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, with jack and tools, with spare tire, with LTO plate, crack on left tail light, handwriting on steering wheel