

General Information

Date & Time: 11, Jul, 2026 14:38

Make	Toyota	Model	Hiace
YOM	2020	Odo Meter Reading	323,931
Registration No.	NEG7306	Chassis No.	JTFNAFAP2K8013880
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	80.5	84	82	75
2	Boot Lid	88.1	87	87	91
3	Roof	91.6	92	83	104/88
4	Left Front Fender	78.2	75	79	80
5	Left Front Door	79.8	80	82	78
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	85.2	84	85	87
9	Right Front Fender	123.6	133	131	107
10	Right Front Door	82.1	79	84	83
11	Center Panel Right	88.4	85	91	89
12	Right Rear Door	87.5	93	88	82
13	Right Back Panel	93.3	93	87	100

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Inspector Notes
with LTO plate, with spare tire, with warranty and manual booklet, no tools and jack, issue on windshield, issue on hood, scratches and dent on exterior, scratches and crack in taillight and headlight, no spare key.