

General Information

Date & Time: 23, Jun, 2026 20:31

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	24,024
Registration No.	FAT8131	Chassis No.	PAHACACA3S6424462
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	88.4	90	86	89
2	Boot Lid	40.3	44	36	41
3	Roof	100.2	102	92	111/96
4	Left Front Fender	87.0	87	89	86
5	Left Front Door	84.0	86	86	80
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	60.4	57	70	55
9	Right Front Fender	86.8	85	91	84
10	Right Front Door	86.3	83	86	91
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	56.1	62	53	54

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : E	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Large / (L) Front Seat - Grime - Large / (L) Front Seat belt - Grime - Large / Overall Interior - Smell - Yes / (R) Front Seat - Grime - Large / Console, Switchs, Vents - Worked - Large / (R) Front Floor Mat - Grime - Large / (L) Front Floor Mat - Grime - Large	Remarks (R) Front Fender, Molding - Repair mark - Difference in Color / (R) Front Fender, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Dent - Large / (R) Mirror - Crack - Damaged / (R) Step, In-panel, Side Spoiler - Repair mark - Difference in Color / (R) Side Gate - Scratch - Large / Cargo Bed Floor - Rust, Corrosion - Large / Rear Gate - Scratch & Dent - Medium / (L) Side Gate - Scratch - Large / (L) Front Door, Molding - Dent - Small / (L) Front Fender, Molding - Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate, with spare tire, with jack, no tools, with warranty booklet, possible fllooded, with smell, with spare key