

General Information

Date & Time: 22, Jun, 2026 15:04

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	28,522
Registration No.	DBU1217	Chassis No.	PAHACACA2S6423643
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.6	101	109	95
2	Boot Lid	54.4	55	57	52
3	Roof	116.2	119	123	114/109
4	Left Front Fender	109.6	104	111	114
5	Left Front Door	108.3	108	110	107
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	69.4	66	76	66
9	Right Front Fender	102.5	106	105	97
10	Right Front Door	105.6	100	108	109
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	71.7	73	73	69

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / (R) Front Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Seat - Worn - Yes / Ceiling - Crinkle - Small	Remarks (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Side Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Rear Gate - Scratch - Small / Cargo Bed Floor - Scratch - Large / (L) Side Gate - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Roof - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/with warranty booklet/with incomplete tools with jack/with spare tire/rear aircon vent missing/hairline scratches on the body/no reverse camera/no spare key