

General Information

Date & Time: 24, Feb, 2025 08:56

Make	Toyota	Model	Innova
YOM	2024	Mileage	20,311
Registration No.	NKB8724	Chassis No.	PA2JA8EM2P0133039
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.6	120	129	110
2	Boot Lid	96.8	95	94	102
3	Roof	96.9	97	91	101/99
4	Left Front Fender	101.4	98	102	104
5	Left Front Door	105.9	100	118	100
6	Center Panel Left				
7	Left Rear Door	111.3	106	119	109
8	Left Back Panel	108.0	107	112	105
9	Right Front Fender	100.7	102	106	94
10	Right Front Door	100.6	100	102	100
11	Center Panel Right				
12	Right Rear Door	98.8	100	100	97
13	Right Back Panel	107.2	115	100	107

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (L) Mirror - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Wheel, Cover - Scratch, Corrosion - Small / (R) Front Wheel, Cover - Scratch, Corrosion - Small
Frame Evaluation : A	Functional Evaluation : D
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Shift Shock - Function - Weak

Inspector Notes
with LTO plate with spare tire/with warranty booklet/No jack and tools/ transmission issue/ check engine light/ abnormal shift shock