

General Information

Date & Time: 27, Jul, 2026 15:29

Make	Toyota	Model	Innova
YOM	2023	Odo Meter Reading	1
Registration No.	DBI3935	Chassis No.	PA2JA8EMXP0125979
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Red Mica Metallic		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	N / A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain			
Remarks Defects not found		Remarks Defects not found	
Frame Evaluation :	N / A	Functional Evaluation :	N / A
Remarks Defects not found		Remarks Defects not found	

Inspector Notes
with lto plate/non moving no key/interior cannot verify due to no key/functionality cannot verify due to no key/mileage cannot verify due to non moving units