

General Information

Date & Time: 25, Feb, 2025 08:44

Make	Toyota	Model	Wigo
YOM	2021	Mileage	86,660
Registration No.	CBK3389	Chassis No.	MHKA4DE5FMJ015850
CC	1.0	Transmission	M/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	75.7	74	87	66
2	Boot Lid	82.5	81	84	83
3	Roof	61.2	49	71	63/62
4	Left Front Fender	73.8	77	76	68
5	Left Front Door	76.8	78	76	76
6	Center Panel Left				
7	Left Rear Door	74.0	81	71	70
8	Left Back Panel	76.5	88	66	75
9	Right Front Fender	75.2	76	79	71
10	Right Front Door	80.2	85	81	74
11	Center Panel Right				
12	Right Rear Door	79.6	79	77	83
13	Right Back Panel	83.8	90	77	85

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Rear Trim - Worked - Small / (R) Front Trim - Worked - Small / (R) Front Seat - Grime - Small / Carpet - Worn, Scratch, Cut, Crack - Small / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Seat - Worn - Yes / Ceiling - Grime - Medium / Trim Other - Cut, Crack - Minimal / Dashboard - Traces of Adhesive Tape - Yes / Trunk Room - Worked - Large / Knobs - Worn, Peel, Crack - Small	Remarks (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Repair mark - Yes / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes

Inspector Notes

with warranty booklet, with jack, no tools, with spare tire, with LTO plate, check engine warning lamp on, reverse light issue