

General Information

Date & Time: 22, Jun, 2026 15:17

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	25,495
Registration No.	NEZ9461	Chassis No.	PAHACACA1S6431264
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.9	116	115	99
2	Boot Lid	69.4	66	57	85
3	Roof	111.4	135	121	124/66
4	Left Front Fender	118.6	115	120	121
5	Left Front Door	125.0	121	131	123
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	73.6	71	68	82
9	Right Front Fender	112.3	114	110	113
10	Right Front Door	112.6	113	114	111
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	67.9	69	65	71

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / Console, Switchs, Vents - Traces of Adhesive Tape - Yes / Ceiling - Grime - Minimal / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Worked - Small / Overall Interior - Smell - Yes	Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch - Minimal / Rear Gate - Scratch - Minimal / Cargo Bed Floor - Scratch - Large / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Side Gate - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

with Ito plate/with manual and warranty booklet/with spare tire/with spare key/with hairlines scratches on the body/with tools and jack/