

General Information

Date & Time: 25, Feb, 2025 13:40

Make	Suzuki	Model	Carry
YOM	2024	Mileage	9,963
Registration No.	NKB8580	Chassis No.	MHYDC61T4RJ212164
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.4	115	95	109
2	Boot Lid	132.3	122	136	139
3	Roof	99.6	118	103	85/92
4	Left Front Fender	104.6	112	95	107
5	Left Front Door	106.6	106	111	103
6	Center Panel Left	101.1	96	97	110
7	Left Rear Door				
8	Left Back Panel	137.6	150	141	122
9	Right Front Fender	112.3	106	114	117
10	Right Front Door	103.4	102	113	95
11	Center Panel Right	100.9	103	110	90
12	Right Rear Door				
13	Right Back Panel	155.6	149	185	133

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Rear Corner Panel - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Side Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Side Gate - Dent - Small / (L) Front Door, Molding - Scratch - Small / Roof - Scratch - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Door Lock - Issue - Yes / Reverse Camera - N/A - Yes

Inspector Notes

with warranty booklet/ with spare tire and tools/ with jack and LTO Plate