

General Information

Date & Time: 19, Jun, 2026 14:40

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	52,471
Registration No.	FAQ6685	Chassis No.	PA1B1F3XR4249602
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	132.0	101	96	199
2	Boot Lid	99.9	98	100	102
3	Roof	89.4	90	91	86/91
4	Left Front Fender	91.5	96	90	89
5	Left Front Door	90.1	90	90	90
6	Center Panel Left				
7	Left Rear Door	96.5	102	99	88
8	Left Back Panel	118.3	105	101	149
9	Right Front Fender	91.9	92	87	96
10	Right Front Door	109.5	96	129	104
11	Center Panel Right				
12	Right Rear Door	91.4	91	93	91
13	Right Back Panel	102.8	96	96	117

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Small	Remarks (R) Front Door - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (R) Mirror - Scratch, Peeled - Minimal / Rear Bumper, Lamps, Panels - Repair mark - Yes / Bonnet, Headlight - Dent - Minimal / (L) Mirror - Scratch, Peeled - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Crack, Gap - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with Ito plate, no warranty booklet, hairline scratch in the body, no spare tier, with jack, no tools