

General Information

Date & Time: 11, Jul, 2026 14:35

Make	Toyota	Model	Avanza
YOM	2016	Odo Meter Reading	304,810
Registration No.	NBW4129	Chassis No.	MHKM5EE1F0K000067
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Beige		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	137.3	130	125	157
2	Boot Lid	113.0	117	107	115
3	Roof	95.1	93	86	105/97
4	Left Front Fender	106.6	103	105	112
5	Left Front Door	114.0	113	119	110
6	Center Panel Left				
7	Left Rear Door	118.3	110	127	118
8	Left Back Panel	110.3	110	109	112
9	Right Front Fender	110.0	104	109	117
10	Right Front Door	113.3	108	115	117
11	Center Panel Right				
12	Right Rear Door	114.3	110	118	115
13	Right Back Panel	102.8	106	98	104

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Inspector Notes
with LTO plate, with spare tire and key, no warranty and manual booklet, no tools and jack, no reverse camera, airbag/srs indicator lamp on, scratches and dent on exterior, scratches on taillight and headlight, taillight cracks, center cap on mags partially missing, modified wiring, aircon not function issue.