

General Information

Date & Time: 25, Feb, 2025 18:49

Make	Toyota	Model	Veloz
YOM	2024	Mileage	23,214
Registration No.	DBM4060	Chassis No.	MHFAB1BY7R3085295
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.4	101	87	101
2	Boot Lid	94.3	90	102	91
3	Roof	109.5	114	117	100/107
4	Left Front Fender	94.3	95	91	96
5	Left Front Door	110.0	108	108	114
6	Center Panel Left				
7	Left Rear Door	101.7	105	99	101
8	Left Back Panel	104.0	107	104	101
9	Right Front Fender	94.1	95	94	93
10	Right Front Door	108.6	109	112	105
11	Center Panel Right				
12	Right Rear Door	103.0	105	101	103
13	Right Back Panel	111.0	105	112	116

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / Trunk Room - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Grime - Medium / Sunvisor, Sunglass Holder - Grime - Small	Remarks Bonnet, Headlight - Dent - Small / (L) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet, spare tire, jack. without tools. with LTO plate.