


General Information

Date & Time: 25, Feb, 2025 16:04

Make	Suzuki	Model	APV
YOM	2023	Mileage	8,390
Registration No.	NIP5165	Chassis No.	130123000097904
CC	1.6	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.8	101	108	99
2	Boot Lid	115.0	106	126	113
3	Roof	97.1	90	94	100/104
4	Left Front Fender	98.8	88	100	109
5	Left Front Door	126.3	121	129	129
6	Center Panel Left				
7	Left Rear Door	127.6	129	126	128
8	Left Back Panel	115.0	119	111	115
9	Right Front Fender	114.0	119	115	108
10	Right Front Door	124.3	132	123	118
11	Center Panel Right				
12	Right Rear Door	127.0	123	124	134
13	Right Back Panel	118.6	116	113	127

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/No reverse camera/No jack and tools