

General Information

Date & Time: 24, Jun, 2026 16:30

Make	Toyota	Model	Vios
YOM	2021	Odo Meter Reading	56,029
Registration No.	DBF3941	Chassis No.	PA1B18F32M4159711
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.0	115	101	111
2	Boot Lid	118.0	123	110	121
3	Roof	92.4	94	88	91/98
4	Left Front Fender	96.5	91	100	99
5	Left Front Door	101.3	100	100	104
6	Center Panel Left				
7	Left Rear Door	99.3	100	97	101
8	Left Back Panel	108.0	106	109	109
9	Right Front Fender	102.9	108	101	100
10	Right Front Door	106.6	104	109	107
11	Center Panel Right				
12	Right Rear Door	104.0	102	100	110
13	Right Back Panel	105.6	104	102	111

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / (R) Front Trim - Grime - Minimal / Glove Box - Worked - Minimal / (L) Front Trim - Grime - Minimal / (L) Front Floor Mat - Worked - Small / Carpet - Worked - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Tyre - Crack, Cut - Yes / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, 1key, no warranty booklet and tools, no spare tire and jack, scratches on headlights and taillights,