

General Information

Date & Time: 25, Jun, 2026 07:29

Make	Toyota	Model	Raize
YOM	2023	Odo Meter Reading	12,847
Registration No.	NIN4036	Chassis No.	MHKAA1BA4PJ080393
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.3	104	124	103
2	Boot Lid	140.6	126	168	128
3	Roof	97.5	108	107	86/89
4	Left Front Fender	93.9	95	105	82
5	Left Front Door	101.8	99	105	102
6	Center Panel Left				
7	Left Rear Door	98.8	101	98	98
8	Left Back Panel	96.0	92	96	100
9	Right Front Fender	103.7	101	115	95
10	Right Front Door	101.2	103	104	97
11	Center Panel Right				
12	Right Rear Door	99.9	95	104	101
13	Right Back Panel	97.3	101	104	87

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
no warranty booklet/ light scratches around the exterior/ no tools/ with jack and spare tire/ with LTO Plate/