

General Information

Date & Time: 25, Feb, 2025 16:45

Make	Toyota	Model	Vios
YOM	2014	Mileage	133,046
Registration No.	WQK353	Chassis No.	NCP1512009356
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Brown		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	126.0	125	130	123
2	Boot Lid	110.3	121	103	107
3	Roof	109.0	101	124	110/101
4	Left Front Fender	104.1	108	110	95
5	Left Front Door	116.0	123	115	110
6	Center Panel Left				
7	Left Rear Door	113.3	114	113	113
8	Left Back Panel	117.3	129	107	116
9	Right Front Fender	106.0	108	111	99
10	Right Front Door	118.3	113	137	105
11	Center Panel Right				
12	Right Rear Door	119.6	115	119	125
13	Right Back Panel	124.0	112	132	128

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Rear Trim - Worked - Small / (L) Front Floor Mat - Cut, Crack - Minimal / Dashboard - Traces of Adhesive Tape - Yes	Remarks (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Small / Antennae - Damaged - Yes / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Mirror - Crack - Damaged / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch & Dent - Small / Roof - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Reverse Camera - N/A - Yes

Inspector Notes
no warranty booklet, with jack and tools, with spare tire, with LTO plate, retractable mirror issue, trunk hood lever not working, backseat cover missing