

General Information

Date & Time: 23, Jun, 2026 20:07

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	18,021
Registration No.	FAS8045	Chassis No.	MHKAA1BCXRJ033874
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	95.8	94	94	99
2	Boot Lid	87.1	83	90	88
3	Roof	83.1	84	81	87/81
4	Left Front Fender	89.3	88	94	87
5	Left Front Door	99.0	99	100	98
6	Center Panel Left				
7	Left Rear Door	94.0	101	90	92
8	Left Back Panel	85.4	83	91	83
9	Right Front Fender	86.4	81	87	91
10	Right Front Door	90.5	91	89	92
11	Center Panel Right				
12	Right Rear Door	89.8	93	88	88
13	Right Back Panel	83.3	83	82	85

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

with lto plate, with spare tire, with jack, incomplete tools, hairline scratches in the body, 1 spare key