


General Information

Date & Time: 26, Feb, 2025 08:44

Make	Toyota	Model	Vios
YOM	2024	Mileage	40,448
Registration No.	NIO9701	Chassis No.	PA1B18F30P4234894
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	157.0	155	154	162
2	Boot Lid	128.6	127	129	130
3	Roof	135.5	135	149	132/126
4	Left Front Fender	137.3	134	137	141
5	Left Front Door	137.0	134	138	139
6	Center Panel Left				
7	Left Rear Door	147.6	159	146	138
8	Left Back Panel	142.0	166	141	119
9	Right Front Fender	146.0	158	132	148
10	Right Front Door	118.0	131	107	116
11	Center Panel Right				
12	Right Rear Door	122.0	124	114	128
13	Right Back Panel	127.0	123	126	132

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Medium / Rear Seat - Grime - Small / (R) Front Seat - Grime - Small / (R) Front Floor Mat - Grime - Medium	Remarks (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Dent - Small / Trunk Hood, Rear Gate - Dent - Small / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Large / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / Roof - Dent - Small / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate/with spare tire/jack and tools/without warranty booklet and reverse camera