

General Information

Date & Time: 26, Feb, 2025 13:52

Make	Toyota	Model	Vios
YOM	2023	Mileage	8,873
Registration No.	NIP5624	Chassis No.	PA1B18F33P4207592
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.6	102	112	106
2	Boot Lid	103.0	100	102	107
3	Roof	96.8	96	86	113/92
4	Left Front Fender	91.8	94	93	89
5	Left Front Door	90.3	88	88	96
6	Center Panel Left				
7	Left Rear Door	94.8	102	91	91
8	Left Back Panel	98.0	100	96	98
9	Right Front Fender	83.1	82	84	84
10	Right Front Door	85.2	87	84	84
11	Center Panel Right				
12	Right Rear Door	95.1	90	99	97
13	Right Back Panel	93.3	94	92	94

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Animal Hair - Yes / Rear Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small	Remarks Bonnet, Headlight - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
head unit display damaged. with warranty booklet, jack, spare tire but incomplete tools. NO LTO plate.