

General Information

Date & Time: 25, Feb, 2025 17:09

Make	Toyota	Model	Vios
YOM	2024	Mileage	5,048
Registration No.	NKA4108	Chassis No.	PA1B18F30R4243405
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.2	105	98	107
2	Boot Lid	98.3	96	94	105
3	Roof	100.6	105	98	93/106
4	Left Front Fender	94.6	99	92	93
5	Left Front Door	92.5	96	91	91
6	Center Panel Left				
7	Left Rear Door	96.7	98	101	92
8	Left Back Panel	105.2	111	107	98
9	Right Front Fender	100.2	105	96	100
10	Right Front Door	101.3	102	102	100
11	Center Panel Right				
12	Right Rear Door	104.4	95	104	114
13	Right Back Panel	103.3	100	101	109

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
rear camera issue/ with warranty booklet and tools/ with jack and spare tire/ with LTO plate