


General Information

Date & Time: 25, Feb, 2025 17:01

Make	Toyota	Model	Vios
YOM	2024	Mileage	5,477
Registration No.	NHS2131	Chassis No.	PA1B18F3XR4241614
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	136.0	133	135	140
2	Boot Lid	129.3	132	126	130
3	Roof	120.7	133	117	120/113
4	Left Front Fender	126.0	129	118	131
5	Left Front Door	130.3	131	133	127
6	Center Panel Left				
7	Left Rear Door	129.3	141	124	123
8	Left Back Panel	132.6	142	133	123
9	Right Front Fender	126.0	128	122	128
10	Right Front Door	109.0	116	103	108
11	Center Panel Right				
12	Right Rear Door	109.6	107	105	117
13	Right Back Panel	123.3	114	123	133

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Defects not found
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate/with spare tire/with warranty booklet/jack and incomplete tools