

General Information

Date & Time: 30, Jun, 2026 21:35

Make	Toyota	Model	Rush
YOM	2024	Odo Meter Reading	26,635
Registration No.	FAR2493	Chassis No.	MHKE8FF3PRK060029
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	77.6	81	71	82
2	Boot Lid	79.6	81	79	79
3	Roof	79.0	71	76	81/88
4	Left Front Fender	94.5	98	93	92
5	Left Front Door	92.5	86	89	102
6	Center Panel Left				
7	Left Rear Door	93.6	102	91	88
8	Left Back Panel	86.0	95	89	75
9	Right Front Fender	88.3	91	87	88
10	Right Front Door	94.8	99	93	92
11	Center Panel Right				
12	Right Rear Door	90.7	88	89	96
13	Right Back Panel	92.4	86	93	99

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small	Remarks (R) Front Fender, Molding - Scratch - Small / Supplemental Mirror - Scratch, Peeled - Minimal / (R) Front Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Audio, Radio - Issue - Yes

Inspector Notes

with Ito plate, with warranty booklet, stereo not working, reverse cam not working, left tail light concern, hairline scratches in the body, with jack, with tools, with spare tire