

General Information

Date & Time: 25, Feb, 2025 17:40

Make	Toyota	Model	Vios
YOM	2024	Mileage	4,500
Registration No.	NHR3073	Chassis No.	PA1B18F3XP4228567
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.6	105	102	107
2	Boot Lid	96.5	93	97	100
3	Roof	96.0	100	101	88/95
4	Left Front Fender	89.3	91	89	88
5	Left Front Door	89.2	91	87	89
6	Center Panel Left				
7	Left Rear Door	100.2	99	101	101
8	Left Back Panel	100.2	100	98	103
9	Right Front Fender	95.4	96	93	98
10	Right Front Door	97.9	102	97	95
11	Center Panel Right				
12	Right Rear Door	97.8	96	96	101
13	Right Back Panel	102.3	103	102	102

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium	Remarks (L) Front Wheel, Cover - Cap Missing - Yes / (L) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
crack right tail light. with spare tire, warranty booklet but incomplete tools. without jack. with LTO plate.