

General Information

Date & Time: 07, Jul, 2026 15:45

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	114,193
Registration No.	GAK8575	Chassis No.	PA1B18F34P4211800
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	126.3	129	132	118
2	Boot Lid	119.3	113	113	132
3	Roof	104.3	110	100	98/109
4	Left Front Fender	115.6	116	112	119
5	Left Front Door	110.0	102	115	113
6	Center Panel Left				
7	Left Rear Door	108.6	114	106	106
8	Left Back Panel	120.3	124	124	113
9	Right Front Fender	105.0	106	105	104
10	Right Front Door	111.3	109	112	113
11	Center Panel Right				
12	Right Rear Door	508.0	237	387	900
13	Right Back Panel	481.3	392	249	803

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
The diagram shows the interior of a vehicle from a top-down perspective. The front seats are labeled Y2. The rear seat is labeled Y2. The dashboard area is labeled Y2. The center console is labeled D. The floor mats are labeled Y4 and Y2. The trunk area is labeled Y2. A small label 8 is at the bottom.		The diagram shows three views of a vehicle's exterior. The front view has labels A3 and A2. The left side view has labels A1, A3, A2, A3, A4, 6, and 10. The right side view has labels A3, A4, A4, A2, 5, 3, and 4. The rear view has labels 13, 14, A2, 15, and AU4.	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Rear Seat - Grime - Small / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Large / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (R) Front Floor Mat - Grime - Minimal / (L) Front Floor Mat - Grime - Small / Mat Other - Grime - Small / Overall Interior - Animal Hair - Yes / Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Rear Trim - Grime - Small / Instrument Panel - Traces of Adhesive Tape - Yes		Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Front Fender, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Repair mark - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Minimal	
Frame Evaluation :	A	Functional Evaluation :	B
Remarks Defects not found		Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes	

Inspector Notes

Possible flooded. Incomplete tools. Right rear door and Fender Molding have repaired marks. Gap at rear bumper. With warranty booklet, seatcover, sparetire, jack, LTO PLate and 3keys.