

General Information

Date & Time: 08, Jul, 2026 07:43

Make	Suzuki	Model	Jimny
YOM	2024	Odo Meter Reading	38
Registration No.	DCG7792	Chassis No.	MA3JC74W9R0155868
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.3	120	115	117
2	Boot Lid	112.6	111	112	115
3	Roof	121.0	115	118	116/135
4	Left Front Fender	114.0	119	112	111
5	Left Front Door	112.0	111	113	112
6	Center Panel Left				
7	Left Rear Door	113.3	113	116	111
8	Left Back Panel	124.3	113	139	121
9	Right Front Fender	115.6	117	113	117
10	Right Front Door	103.9	94	109	109
11	Center Panel Right				
12	Right Rear Door	116.3	118	113	118
13	Right Back Panel	119.3	114	118	126

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Remote Key & Smart entry - Issue - Yes

Inspector Notes
with warranty booklet, jack and tools, with spare tire, with LTO plate