

General Information

Date & Time: 26, Feb, 2025 12:18

Make	Toyota	Model	Vios
YOM	2024	Mileage	5,487
Registration No.	DBO8287	Chassis No.	PA1B18F32R4257998
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	160.6	159	149	174
2	Boot Lid	150.0	159	139	152
3	Roof	154.7	161	149	158/151
4	Left Front Fender	138.0	139	140	135
5	Left Front Door	131.6	133	131	131
6	Center Panel Left				
7	Left Rear Door	149.3	147	159	142
8	Left Back Panel	161.0	187	153	143
9	Right Front Fender	150.3	150	138	163
10	Right Front Door	145.3	153	140	143
11	Center Panel Right				
12	Right Rear Door	154.3	148	148	167
13	Right Back Panel	141.6	129	144	152

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Medium / (L) Front Floor Mat - Worked - Large / (L) Front Seat - Grime - Medium / (L) Front Trim - Worked - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Minimal / (R) Front Floor Mat - Worked - Small / Ceiling - Grime - Minimal	Remarks (L) Rear Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes

no warranty booklet, with jack and tools, with spare tire, with LTO plate