

General Information

Date & Time: 26, Feb, 2025 10:23

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,150
Registration No.	NHN6309	Chassis No.	PA1B18F36R4245756
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.6	110	105	102
2	Boot Lid	98.0	96	98	100
3	Roof	103.3	107	99	95/112
4	Left Front Fender	91.6	94	90	91
5	Left Front Door	91.6	86	95	94
6	Center Panel Left				
7	Left Rear Door	99.3	99	100	99
8	Left Back Panel	103.0	111	100	98
9	Right Front Fender	107.0	120	100	101
10	Right Front Door	102.4	108	100	99
11	Center Panel Right				
12	Right Rear Door	101.8	95	99	112
13	Right Back Panel	107.6	106	107	110

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / Mat Other - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small	Remarks (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Medium / Roof - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet, with jack and tools, with spare tire, with LTO plate