

General Information

Date & Time: 11, Jul, 2026 15:26

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	33,975
Registration No.	NEZ8157	Chassis No.	PAHACACA1S6428364
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.0	115	119	114
2	Boot Lid	66.5	65	62	72
3	Roof	109.7	110	117	104/108
4	Left Front Fender	104.9	104	111	100
5	Left Front Door	110.0	110	112	108
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	69.7	67	71	71
9	Right Front Fender	112.0	109	117	110
10	Right Front Door	109.0	107	109	111
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	69.2	68	69	71

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Small / Ceiling - Grime - Large	Remarks Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Side Gate - Scratch - Medium / Roof - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Side Gate - Scratch & Dent - Large / Rear Gate - Scratch - Small / (R) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

With warranty booklet and spare tire. Without jack and tools. 1 key. With LTO plate.