

General Information

Date & Time: 11, Jul, 2026 14:25

Make	Toyota	Model	Hilux
YOM	2026	Odo Meter Reading	8,713
Registration No.	DCC9520	Chassis No.	MR0DB8CD9S0135281
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	109	116	103
2	Boot Lid	85.8	91	84	83
3	Roof	100.5	102	98	103/100
4	Left Front Fender	97.2	106	89	97
5	Left Front Door	97.6	101	99	93
6	Center Panel Left				
7	Left Rear Door	93.0	94	90	96
8	Left Back Panel	98.9	97	93	107
9	Right Front Fender	91.6	100	85	90
10	Right Front Door	102.4	99	103	105
11	Center Panel Right				
12	Right Rear Door	97.1	95	96	100
13	Right Back Panel	93.6	100	94	87

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Grime - Minimal / (R) Front Floor Mat - Grime - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Minimal / Ceiling - Grime - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Side Gate - Scratch - Minimal / Cargo Bed Floor - Scratch - Minimal / Rear Gate - Scratch - Minimal / (L) Side Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
without lto plate/with jack no tools/without reverse camera/with warranty booklet/with hairlines scratches on the body/with spare key/modified power window