

General Information

Date & Time: 15, Jul, 2026 12:06

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	5,470
Registration No.	CCQ5232	Chassis No.	PAHACACA5S64327833
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.9	107	108	97
2	Boot Lid	65.6	66	66	65
3	Roof	114.2	125	117	104/111
4	Left Front Fender	106.3	108	103	108
5	Left Front Door	99.9	99	101	100
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	69.5	63	74	72
9	Right Front Fender	106.7	112	109	99
10	Right Front Door	104.3	102	106	105
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	63.0	68	58	63

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Carpet - Worked - Minimal / (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Side Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Dent - Medium / Rear Gate - Scratch - Minimal / Cargo Bed Floor - Scratch - Large / (L) Side Gate - Scratch - Minimal / Roof - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

With Lto plate, with spare tire, with warranty booklet, 2keys, no jack and tools, scratches on headlights