

General Information

Date & Time: 01, Mar, 2025 10:30

Make	Toyota	Model	Vios
YOM	2024	Mileage	12,734
Registration No.	CBB6189	Chassis No.	PA1B18F39P4232416
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	137.6	134	133	146
2	Boot Lid	124.0	122	126	124
3	Roof	123.5	134	127	114/119
4	Left Front Fender	125.6	122	124	131
5	Left Front Door	123.6	123	126	122
6	Center Panel Left				
7	Left Rear Door	124.3	129	124	120
8	Left Back Panel	140.0	138	151	131
9	Right Front Fender	137.3	144	136	132
10	Right Front Door	118.0	116	124	114
11	Center Panel Right				
12	Right Rear Door	119.0	126	111	120
13	Right Back Panel	133.6	123	123	155

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trunk Room - Worn, Scratch, Cut, Crack - Minimal	Remarks (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / Roof - Dent - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/jack and tools/with warranty booklets/No reverse camera