

General Information

Date & Time: 15, Jul, 2026 15:14

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	36,566
Registration No.	NJC9218	Chassis No.	PAHACACA3S6425661
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.1	109	110	100
2	Boot Lid	62.4	64	64	60
3	Roof	122.7	130	125	121/115
4	Left Front Fender	107.3	104	105	113
5	Left Front Door	107.0	103	112	106
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	65.7	59	69	69
9	Right Front Fender	107.0	115	110	96
10	Right Front Door	106.0	101	107	110
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	74.1	74	74	74

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / Display, Audio System - Missing - Yes / (L) Front Floor Mat - Worked - Small / Carpet - Worked - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Side Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Minimal / Cab Back Panel - Scratch - Large / (L) Side Gate - Scratch & Dent - Small / Roof - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Head Light, High Beam - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

With Lto plate, with spare tire and jack, with warranty booklet, 1key, scratches on headlights, no Rear door key