

General Information

Date & Time: 15, Jul, 2026 12:07

Make	Toyota	Model	Vios
YOM	2026	Odo Meter Reading	11,742
Registration No.	DCE4016	Chassis No.	PA1B18F34S4306656
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.0	117	116	115
2	Boot Lid	120.0	119	116	125
3	Roof	103.4	106	103	100/105
4	Left Front Fender	104.6	104	104	106
5	Left Front Door	102.4	107	105	95
6	Center Panel Left				
7	Left Rear Door	107.0	101	106	114
8	Left Back Panel	120.3	131	119	111
9	Right Front Fender	106.3	105	109	105
10	Right Front Door	110.0	122	103	105
11	Center Panel Right				
12	Right Rear Door	114.3	113	115	115
13	Right Back Panel	112.6	105	107	126

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / Mat Other - Missing - Yes / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes

Inspector Notes

With Lto plate, with warranty booklet and jack, 3keys, no spare tire and tools, scratches on headlights and taillights,check engine warning lamp on, traction control lamp on, maintenance warning lamp on,