

General Information

Date & Time: 14, Jul, 2026 15:53

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	22,509
Registration No.	NHS5427	Chassis No.	PA1B18F39R4262518
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	111	109	113
2	Boot Lid	115.3	114	115	117
3	Roof	102.3	104	99	101/105
4	Left Front Fender	104.6	108	102	104
5	Left Front Door	102.3	105	100	102
6	Center Panel Left				
7	Left Rear Door	114.6	120	120	104
8	Left Back Panel	115.3	118	112	116
9	Right Front Fender	109.3	106	109	113
10	Right Front Door	112.3	112	116	109
11	Center Panel Right				
12	Right Rear Door	113.3	116	112	112
13	Right Back Panel	111.0	108	105	120

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / Rear Seat - Grime - Small / (R) Front Floor Mat - Worked - Small / (L) Front Floor Mat - Cut, Crack - Small / (R) Front Seat - Grime - Minimal / (L) Front Seat - Worn - Yes / Dashboard - Loose, Deformed - Medium	Remarks (R) Front Fender, Molding - Crack, Gap - Small / (R) Front Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Repair mark - Yes / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Front Bumper, Grille, Lamps - Repair mark - Yes / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : D
Remarks Defects not found	Remarks Panel, Meter - Issue - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Horn - Issue - Yes / Seat Belts - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/warranty booklet/no tools and jack/no spare tire/no spare key/aircon issue/tailight issue/tailight cover cracked/signal light issue/brake light issue/traction control switch issue/side mirror issue/seat belt issue and missing/rpm meter issue/rough idling/abnormal engine vibration/horn issue/traces of adhesive on exterior/replaced front bumper/no fog lights/hairline scratches on the body/rear fender liner missing