

General Information

Date & Time: 14, Jul, 2026 16:47

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	21,739
Registration No.	GBJ6752	Chassis No.	MHFAB1BY8R3130048
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	124.6	124	126	124
2	Boot Lid	112.0	112	116	108
3	Roof	124.5	133	129	118/118
4	Left Front Fender	107.3	106	108	108
5	Left Front Door	134.0	129	135	138
6	Center Panel Left				
7	Left Rear Door	124.3	124	126	123
8	Left Back Panel	129.0	140	130	117
9	Right Front Fender	117.3	117	117	118
10	Right Front Door	127.0	132	126	123
11	Center Panel Right				
12	Right Rear Door	121.0	122	117	124
13	Right Back Panel	123.6	116	126	129

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Animal Hair - Yes / Ceiling - Grime - Small / Glove Box - Worn, Scratch, Cut, Crack - Minimal / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / (R) Front Seat - Grime - Minimal / Trim Other - Grime - Minimal / Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / Trim Other - Grime - Minimal	Remarks Bonnet, Headlight - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Dent - Large / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
HPG recovered. With paint marks at the right rear bumper. Minimal scratches at the exterior. Without LTO PLate, seatcover,Jack, and tools. With Warranty booklet. sparetire and 1 key.