

General Information

Date & Time: 14, Jul, 2026 16:43

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	6,199
Registration No.	GBK7388	Chassis No.	PAHACACAXS6425415
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.3	118	113	118
2	Boot Lid	71.1	90	58	66
3	Roof	125.2	136	124	118/123
4	Left Front Fender	120.0	122	123	115
5	Left Front Door	118.0	119	117	118
6	Center Panel Left	95.8	121	81	86
7	Left Rear Door				
8	Left Back Panel	76.4	82	80	68
9	Right Front Fender	119.3	115	119	124
10	Right Front Door	115.0	109	117	119
11	Center Panel Right	85.3	85	81	90
12	Right Rear Door				
13	Right Back Panel	85.3	74	107	75

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Minimal / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Rear Seat - Grime - Small / Overall Interior - Animal Hair - Yes	Remarks (L) Front Fender, Molding - Scratch - Large / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Side Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Dent - Medium / (L) Side Gate - Scratch - Large / (L) Front Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
Without Back panel window, seatcover, LTO plate. With warranty booklet, sparetire, jack, tools and 4keys.