

## General Information

Date & Time: 13, Jul, 2026 16:24

|                  |         |                   |                   |
|------------------|---------|-------------------|-------------------|
| Make             | Toyota  | Model             | Hilux Tamaraw     |
| YOM              | 2025    | Odo Meter Reading | 1                 |
| Registration No. | GBK7955 | Chassis No.       | PAHACACA3S6423666 |
| CC               | 2.4     | Transmission      | M/T               |
| Fuel Type        | Diesel  | Type of Body      | Pickup            |
| Colour           | White   |                   |                   |

## Body / Panel Condition





| #  | Area               | Thickness(um) |        |        |          |
|----|--------------------|---------------|--------|--------|----------|
|    |                    | Average       | Value1 | Value2 | Value3/4 |
| 1  | Bonnet             | 133.0         | 129    | 137    | 133      |
| 2  | Boot Lid           | 63.7          | 69     | 65     | 58       |
| 3  | Roof               | 99.1          | 140    | 132    | 124/1    |
| 4  | Left Front Fender  | 121.3         | 129    | 119    | 116      |
| 5  | Left Front Door    | 117.6         | 122    | 117    | 114      |
| 6  | Center Panel Left  |               |        |        |          |
| 7  | Left Rear Door     |               |        |        |          |
| 8  | Left Back Panel    | 73.0          | 73     | 72     | 74       |
| 9  | Right Front Fender | 120.6         | 121    | 123    | 118      |
| 10 | Right Front Door   | 4.9           | 7      | 7      | 1        |
| 11 | Center Panel Right |               |        |        |          |
| 12 | Right Rear Door    |               |        |        |          |
| 13 | Right Back Panel   | 88.8          | 85     | 97     | 85       |

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

| Interior Evaluation :<br>E                                                                                                                                                                                                                                                                                                                                               | Exterior Evaluation :<br>D                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>                                                                                                                                                                        |  <p>A : Scratch AU : Scratch &amp; Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust &amp; Corrosion U : Dent X : Defective Y : Crack, Gap</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
| <p><b>Remarks</b></p> <p>Overall Interior - Smell - Yes / Overall Interior - Animal Hair - Yes / Ceiling - Grime - Large / Rear Seat - Grime - Large / (R) Front Floor Mat - Grime - Large / (L) Front Floor Mat - Grime - Large / (L) Front Seat - Grime - Large / (R) Front Seat - Grime - Large / (L) Front Trim - Grime - Large / (R) Front Trim - Grime - Large</p> | <p><b>Remarks</b></p> <p>(R) Front Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Large / Front Bumper, Grille, Lamps - Crack, Gap - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Side Gate - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Gate - Scratch - Small / (L) Side Gate - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small</p>                                                                                                                               |
| Frame Evaluation :<br>A                                                                                                                                                                                                                                                                                                                                                  | Functional Evaluation :<br>E                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
| <p><b>Remarks</b></p> <p>Defects not found</p>                                                                                                                                                                                                                                                                                                                           | <p><b>Remarks</b></p> <p>Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Panel, Meter - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Door Lock - Issue - Yes / Power Seat - Issue - Yes / Power Steering - Issue - Yes / Shift Shock - Function - Weak / Air Conditioner - Function - Weak / Power Steering Pump - Leak - Yes / Radiator Water Pump - Leak - Yes / Battery - Weak - Yes / Remote Key &amp; Smart entry - Issue - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Brake Pedal - Function - Weak / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes / Seat Belts - Issue - Yes</p> |

## Inspector Notes

Flooded unit. Non moving unit. Mileage cannot be determined. Functions cannot be determined. Without warranty booklet, tools, seatcover. With Jack, sparetire, LTO plate and 4keys.