

General Information

Date & Time: 14, Jul, 2026 14:33

Make	Toyota	Model	Wigo
YOM	2024	Odo Meter Reading	1
Registration No.	GBH4227	Chassis No.	MHKAA1BC7PJ009724
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Orange		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	147.0	153	151	137
2	Boot Lid	106.0	109	105	104
3	Roof	100.8	104	96	107/97
4	Left Front Fender	102.0	100	102	104
5	Left Front Door	121.6	136	108	121
6	Center Panel Left				
7	Left Rear Door	115.0	122	118	105
8	Left Back Panel	108.3	112	105	108
9	Right Front Fender	161.6	170	165	150
10	Right Front Door	164.0	164	165	163
11	Center Panel Right				
12	Right Rear Door	193.0	170	182	227
13	Right Back Panel	184.3	181	190	182

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
The diagram shows the interior of a vehicle from a top-down perspective. Evaluation points are marked as follows: Y1: Driver's seat. Y2: Passenger's seat. Y3: Rear passenger area. Y4: Front dashboard area. K: Center console area. 8: Rear floor mat area.		The diagram shows the exterior of a vehicle from three perspectives: front, side, and rear. Evaluation points are marked as follows: A1, A2, A3, A4: Various locations on the hood, roof, and rear. G2: Front bumper area. 7, 8, 9, 10, 11, 12: Various locations on the side and rear panels.	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / Mat Other - Grime - Small / (R) Front Seat belt - Grime - Medium / (R) Rear Trim - Grime - Minimal / Rear Seat - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Minimal / Ceiling - Grime - Large / Overall Interior - Smell - Yes / Overall Interior - Animal Hair - Yes		Remarks (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Mirror - Scratch - Small / Front Windshield - Scratch, Stone chip - Small	
Frame Evaluation :	A	Functional Evaluation :	E
Remarks Defects not found		Remarks Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Panel, Meter - Issue - Yes / Door Lock - Issue - Yes / Power Steering - Issue - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Brake Pedal - Function - Weak / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes	

Inspector Notes

Possible flooded. Unusual sound in engine. Power steering issue. Panel board is not working . headlight and taillight issue. AC is not working. Radio and back cam is not working. Mileage cannot be determined. door lock issue. Wiring functions cannot be determined. Without tools, warranty booklet, seatcover. With Jack, sparetire, LTO plate and 2keys.