

General Information

Date & Time: 14, Jul, 2026 14:43

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	14,921
Registration No.	GBF8643	Chassis No.	MHKAA1BC1RJ027882
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Gray		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	130.3	135	125	131
2	Boot Lid	103.5	104	107	100
3	Roof	98.2	117	91	98/87
4	Left Front Fender	105.5	100	116	101
5	Left Front Door	115.0	115	108	122
6	Center Panel Left				
7	Left Rear Door	109.3	111	111	106
8	Left Back Panel	108.3	111	103	111
9	Right Front Fender	98.5	97	104	95
10	Right Front Door	120.6	124	123	115
11	Center Panel Right				
12	Right Rear Door	107.6	102	108	113
13	Right Back Panel	101.6	104	99	102

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Animal Hair - Yes / Ceiling - Grime - Medium / Dashboard - Worn, Scratch, Cut, Crack - Minimal / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / (R) Front Seat - Grime - Minimal / Trim Other - Grime - Minimal / (R) Rear Trim - Grime - Medium / Rear Seat - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Medium / (L) Rear Trim - Grime - Minimal / Trim Other - Grime - Minimal / (L) Front Seat - Grime - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Large / (R) Mirror - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes

Inspector Notes

Incomplete tools. Visible hairline scratches. Left side taillight busted. Repaired marks at left rear fender molding. With warranty booklet, jack, seatcover, sparetire, LTO plate and 2keys.