

General Information

Date & Time: 14, Jul, 2026 14:34

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	14,640
Registration No.	GBK3785	Chassis No.	MHFAA1BY4S0046349
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	126.3	125	126	128
2	Boot Lid	123.3	127	121	122
3	Roof	123.2	132	115	121/125
4	Left Front Fender	119.3	122	118	118
5	Left Front Door	122.0	118	117	131
6	Center Panel Left				
7	Left Rear Door	120.6	124	120	118
8	Left Back Panel	125.0	134	123	118
9	Right Front Fender	116.6	118	123	109
10	Right Front Door	123.0	123	124	122
11	Center Panel Right				
12	Right Rear Door	120.3	123	118	120
13	Right Back Panel	126.6	115	130	135

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Grime - Minimal / (L) Front Floor Mat - Grime - Small / Mat Other - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Minimal / Overall Interior - Animal Hair - Yes / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Trim - Grime - Minimal / (R) Rear Trim - Grime - Minimal / Rear Seat - Grime - Medium / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Small	Remarks (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Dent - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Door Lock - Issue - Yes

Inspector Notes

Rear trunk door cannot be open. Visible hairline scratches. Without warranty booklet, jack, tools, seatcover. With spare tire, LTO plate and 2 keys.