

General Information

Date & Time: 03, Mar, 2025 14:38

Make	Toyota	Model	Vios
YOM	2023	Mileage	30,057
Registration No.	NHA3640	Chassis No.	PA1B18F31P4218140
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.0	121	102	116
2	Boot Lid	108.0	105	109	110
3	Roof	99.5	104	98	99/97
4	Left Front Fender	96.0	100	93	96
5	Left Front Door	94.9	96	96	93
6	Center Panel Left				
7	Left Rear Door	98.8	99	99	99
8	Left Back Panel	103.6	102	102	107
9	Right Front Fender	94.2	93	95	95
10	Right Front Door	99.4	106	95	97
11	Center Panel Right				
12	Right Rear Door	101.0	95	100	108
13	Right Back Panel	104.3	103	102	108

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / Ceiling - Grime - Minimal	Remarks Front Windshield - Damaged - Large / (L) Front Fender, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Roof - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Dent - Small / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, spare tire, jack but incomplete tools. without LTO plate.