

General Information

Date & Time: 14, Jul, 2026 16:46

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	31,727
Registration No.	GBE3825	Chassis No.	PA1B18F33R4255080
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.3	125	118	121
2	Boot Lid	106.6	103	103	114
3	Roof	106.8	105	106	99/117
4	Left Front Fender	114.6	110	113	121
5	Left Front Door	123.3	125	132	113
6	Center Panel Left				
7	Left Rear Door	111.6	112	117	106
8	Left Back Panel	120.0	123	121	116
9	Right Front Fender	108.6	107	109	110
10	Right Front Door	118.0	116	120	118
11	Center Panel Right				
12	Right Rear Door	120.3	118	117	126
13	Right Back Panel	109.0	111	106	110

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Small / (L) Rear Trim - Grime - Minimal / (R) Rear Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Overall Interior - Animal Hair - Yes / Ceiling - Grime - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Small	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Large / (R) Side Window - Scratch, Stone chip - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Dent - Medium / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Dent - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Large
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes
Possible flooded. Large gap at front bumper. Right side headlight crack. Rear both Taillight crack. Incomplete tools. With warranty booklet, seatcover, jack, sparetire, LTO plate and 3keys.