

General Information

Date & Time: 14, Jul, 2026 15:47

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	10,851
Registration No.	NJA8837	Chassis No.	PA1B18F37S4284961
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	114	106	108
2	Boot Lid	119.0	121	120	116
3	Roof	96.6	99	96	97/94
4	Left Front Fender	114.3	113	120	110
5	Left Front Door	106.0	108	104	106
6	Center Panel Left				
7	Left Rear Door	109.9	126	104	100
8	Left Back Panel	254.0	253	348	161
9	Right Front Fender	107.0	105	102	114
10	Right Front Door	104.6	104	109	101
11	Center Panel Right				
12	Right Rear Door	107.6	103	113	107
13	Right Back Panel	110.5	100	107	125

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Animal Hair - Yes / Dashboard - Worn, Scratch, Cut, Crack - Minimal / (R) Front Floor Mat - Grime - Minimal / (L) Front Floor Mat - Grime - Minimal / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Small / Rear Seat - Grime - Minimal / Ceiling - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal	Remarks (L) Rear Fender - Repair Traces - Yes / (R) Front Fender, Molding - Dent - Medium / (R) Front Door, Molding - Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

with lto plate/with warrsnty booklet/with spare tire/with spare key/with tools and jack/with reverse camera/with hairlines sctagches on the body