

General Information

Date & Time: 04, Mar, 2025 15:46

Make	Toyota	Model	Vios
YOM	2024	Mileage	14,909
Registration No.	VAC2176	Chassis No.	PA1B18F38R4249601
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.6	144	107	114
2	Boot Lid	97.3	97	98	97
3	Roof	97.0	100	100	92/96
4	Left Front Fender	93.4	103	85	93
5	Left Front Door	95.2	97	94	95
6	Center Panel Left				
7	Left Rear Door	102.0	118	96	93
8	Left Back Panel	102.8	115	100	94
9	Right Front Fender	97.9	101	95	98
10	Right Front Door	119.2	136	98	124
11	Center Panel Right				
12	Right Rear Door	103.3	99	100	111
13	Right Back Panel	107.5	101	98	124

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small / (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Large / Knobs - Worn, Peel, Crack - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Fender, Molding - Scratch & Dent - Medium / (L) Rear Fender, Molding - Dent - Small / (L) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Dent - Small / (R) Front Door, Molding - Dent - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate/with spare tire/with jack and tools/with warranty booklet