

General Information

Date & Time: 14, Jul, 2026 15:48

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	23,483
Registration No.	NFR2598	Chassis No.	PA1B18F31R4247365
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.6	139	115	108
2	Boot Lid	147.0	130	135	176
3	Roof	109.2	110	110	104/113
4	Left Front Fender	107.3	107	102	113
5	Left Front Door	115.6	120	114	113
6	Center Panel Left				
7	Left Rear Door	119.3	119	122	117
8	Left Back Panel	125.6	132	120	125
9	Right Front Fender	112.0	120	108	108
10	Right Front Door	116.6	110	119	121
11	Center Panel Right				
12	Right Rear Door	120.6	120	125	117
13	Right Back Panel	124.0	122	119	131

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Worn, Scratch, Cut, Crack - Minimal / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Worked - Small / Mat Other - Worked - Small / (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Rear Seat - Grime - Minimal / Ceiling - Grime - Medium	Remarks (R) Front Fender, Molding - Dent - Small / (R) Front Door, Molding - Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Repair mark - Difference in Color / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Dent - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with Ito plate/with warranty booklet/with spare tire/with tools and jack/with hairlines scratches on the body/with reverse camera/without spare key