

General Information

Date & Time: 15, Jul, 2026 15:25

Make	Toyota	Model	Hilux
YOM	2025	Odo Meter Reading	35,577
Registration No.	DBS1477	Chassis No.	MR0AB8DD9R5155058
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	118	113	109
2	Boot Lid	92.5	94	91	93
3	Roof	102.3	96	100	111/102
4	Left Front Fender	104.3	104	108	101
5	Left Front Door	109.0	104	110	113
6	Center Panel Left				
7	Left Rear Door	101.7	106	104	95
8	Left Back Panel	112.6	113	109	116
9	Right Front Fender	107.0	100	106	115
10	Right Front Door	107.3	105	109	108
11	Center Panel Right				
12	Right Rear Door	95.3	90	90	106
13	Right Back Panel	105.2	107	109	100

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Worn, Scratch, Cut, Crack - Minimal / Ceiling - Grime - Minimal / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / (L) Front Floor Mat - Worked - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch - Minimal / Cargo Bed Floor - Scratch - Minimal / Rear Gate - Scratch & Dent - Small / (L) Side Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Shift Shock - Function - Weak / Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with Ito plate/without warranty booklet/with spare tire/with hairlines scratches on the body/with reverse camera/without spare key/replace fuel filter/air conditioned issue