

General Information

Date & Time: 15, Jul, 2026 15:06

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	5,615
Registration No.	NLC3876	Chassis No.	PAHACACA7S6431737
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.6	97	109	98
2	Boot Lid	64.7	72	67	55
3	Roof	114.2	121	119	111/106
4	Left Front Fender	107.0	103	109	109
5	Left Front Door	111.0	110	111	112
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	56.2	50	58	60
9	Right Front Fender	101.8	107	100	99
10	Right Front Door	104.0	101	104	107
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	59.7	55	65	60

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Minimal / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small	Remarks (R) Side Gate - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal / (L) Side Gate - Scratch - Minimal / Cargo Bed Floor - Scratch - Small / Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate/with warranty booklet/with tools and jack/with spare tire/with spare key/with seat cover/hairline scratches on the body