

General Information

Date & Time: 15, Jul, 2026 15:29

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	14,063
Registration No.	EAH5158	Chassis No.	PAHACACA6S6425833
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	158.6	106	120	250
2	Boot Lid	63.6	70	60	62
3	Roof	122.7	119	118	145/109
4	Left Front Fender	103.9	106	108	98
5	Left Front Door	105.0	107	108	100
6	Center Panel Left	100.3	95	94	112
7	Left Rear Door				
8	Left Back Panel	65.5	94	4	98
9	Right Front Fender	109.3	104	114	110
10	Right Front Door	105.0	101	108	106
11	Center Panel Right	110.0	114	111	105
12	Right Rear Door				
13	Right Back Panel	69.1	64	70	73

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Floor Mat - Grime - Medium / (R) Front Floor Mat - Grime - Minimal / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Rear Seat - Grime - Small / Ceiling - Grime - Small	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap Remarks Bonnet - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (L) Side Gate - Scratch & Dent - Small / (L) Guard Frame - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Rear Gate - Scratch & Dent - Small / (R) Guard Frame - Scratch & Dent - Medium / (R) Side Gate - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / Roof - Dent - Small / Bonnet, Headlight - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Cargo Bed Floor - Scratch - Medium / Cab Back Panel - Modified - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with LTO plate, with spare tire, with warranty and manual booklet, no spare key, with scratches and dent on exterior, scratches on taillight and headlight.