

General Information

Date & Time: 14, Jul, 2026 15:46

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	14,224
Registration No.	DCE4758	Chassis No.	PAHACACA5S6433485
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.1	112	104	97
2	Boot Lid	71.7	75	67	73
3	Roof	115.2	125	115	117/104
4	Left Front Fender	112.6	116	111	111
5	Left Front Door	110.6	111	105	116
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	87.7	83	96	84
9	Right Front Fender	111.3	121	107	106
10	Right Front Door	106.8	100	106	115
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	97.2	103	95	94

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Worn, Scratch, Cut, Crack - Minimal / Console, Switchs, Vents - Traces of Adhesive Tape - Yes / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Worked - Small / Ceiling - Grime - Minimal / (L) Front Trim - Cut, Crack - Minimal	Remarks (R) Side Gate - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Dent - Small / Bonnet, Headlight - Scratch - Minimal / Rear Gate - Scratch - Minimal / Cargo Bed Floor - Scratch - Small / Roof - Scratch - Minimal / (L) Side Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with Ito plate/with warranty booklet/with tools and jack/with spare tire/with hairlines scratches on the body/without spare key/without reverse camera