

General Information

Date & Time: 15, Jul, 2026 08:17

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	4,920
Registration No.	DCF6579	Chassis No.	PAHACACA5T6435589
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.6	102	107	135
2	Boot Lid	54.7	58	55	51
3	Roof	114.7	121	125	110/103
4	Left Front Fender	109.3	113	102	113
5	Left Front Door	107.6	111	108	104
6	Center Panel Left	103.4	114	99	97
7	Left Rear Door				
8	Left Back Panel	66.8	70	59	72
9	Right Front Fender	107.7	115	99	109
10	Right Front Door	101.8	99	103	104
11	Center Panel Right	102.3	107	100	100
12	Right Rear Door				
13	Right Back Panel	55.9	52	67	49

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Seat - Grime - Small	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Side Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Gate - Scratch - Small / Cargo Bed Floor - Scratch & Dent - Small / (L) Side Gate - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Modified - Small / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet, jack and tools, with spare tire, with LTO plate, scratches on tail light